

- Site Report -

Date: January 10, 2012 IRD Sales Order: 11167

To: Cindy Mantie From: Bryan Knight

Project Name/Location: LTPP I-10 E MP 49.5, NM

Service Date(s): April 19 2011

Job Description: Maintenance Visit

Work Completed:

- Performed Visual inspection of roadway and inroad sensors. No abnormal wear and tear noted.
- Installed Two (2) new Deep Cycle Sealed 12VDC System Batteries.
- Recorded Electrical readings of Kistlers, Loops, Batteries, and Solar Charging System.
- Found the K7 Kistler of the Downstream array recorded low at 0.3 nF. All other system readings recorded within normal specification.
- Could not log onto the Isinc locally. No WCUII prompt. ESS in Saskatoon reported they could not get a WCUII prompt while attempting log in remotely.
- New W3 upgrade will be done when parts arrive. (ETA for completion April 25 2011)
- Performed general housekeeping on Equipment Cabinet.

6/19/96 IRD FORM No.: 1304A

™INTERNATIONAL ROAD DYNAMICS INC.



702 - 43rd Street East Saskatoon, SK CANADA S7K 3T9 Ph: (306) 653-6600 Fax: (306) 242-5599 <u>www.irdinc.com</u>





702 - 43rd Street East Saskatoon, SK CANADA S7K 3T9 Ph: (306) 653-6600 Fax: (306) 242-5599 <u>www.irdinc.com</u>







702 - 43 $^{\rm rd}$ Street East Saskatoon, SK CANADA S7K 3T9

Ph: (306) 653-6600 Fax: (306) 242-5599 www.irdinc.com



Work Remaining: W3 Upgrade.

Schedule Include Estimate to Complete (on-track, ahead, behind):

Parts Used: Two (2) 12VDC Batteries

Pre-mature Equipment Failure:

Mileage / Travel Time: Total Travel: 10hrs Total Onsite: 2hrs

Safety Concerns: None

Issues Related to Sub-Contractors:

Other Notes:

Action Items:

Item	Action Required	Ownership
1.		
2.		
3.		
4.		